Flash Message: Region 10, , US Ecology Waste Disposal Facility Explosion (Grand View, Idaho) -- UPDATE #1

Subject	Flash Message: Region 10, , US Ecology Waste Disposal Facility Explosion (Grand View, Idaho) UPDATE #1
From	Sheldrake, Beth
То	R10-ECL EMP
Cc	R10-ECL EMP Support; Knudsen, Laura
Sent	Sunday, November 18, 2018 7:01 PM

This message is being sent bcc to the Region 10 Executive Team UNCLASSIFIED//FOR OFFICIAL USE ONLY

©EPA

US Environmental Protection Agency - Region 10
Notification No.: 2200758
Hospital Region 10, US Ecology Waste Disposal Facility Explosion (Grand View, Idaho) – UPDATE #

Flash Message: Region 10, US Ecology Waste Disposal Facility Explosion (Grand View, Idaho) – UPDATE # 1
Report as of: 1700 PST, November 18, 2018
Report as the US Ecology Subtitle C Idisposal facility in Grand View, Owyhee County, Idaho. The explosion took place in a building used to process magnesium power. It was estimated that approximately 7,000 pounds of magnesium powder were present in the building. Magnesium is an alkali metal and reacts strongly when coming in contact with water although the exact cause of the explosion is not definitively known. The initial explosion was followed by a second explosion approximately an hour later.

Three workers from the facility were treated and released from a local hospital and one worker was inlied. The building where the magnesium was located was significantly damaged and the explosion caused damage to surrounding buildings, several of which reportedly contained flammable hazardous waste. Damage from the explosion compromised US Ecology's ability to access and provide definitive information on the chemical contents of the damaged and surrounding structures. There were no initial concerns about impacts to 67-list earl quality.

State, Local and other Federal Agency Actions: The Incident Commander with Owyhee County Sherriff's office requested assistance from a State-wide HaziMat Team with decontamination of the injured workers so they can be admitted to the local hospital for treatment and recovery of the missing worker. Idaho Department of Environmental Quality (IDEO) is providing technical assistance from the HaziMat Team.

Team. The Incident Commander and HaziMat Team demobilized from the scene late Saturday evening after recovery of the fatally injured worker. The facility is regulated under the State of Idaho RGA PROGRAM.

after recovery of the fatally injured worker. The facility is regulated under the State of Idaho RCRA program.
PEPA Actions: EPA OSC Ball responded to the scene from Boise early on Sunday, November 18°, and
formed a Unified Command with US Ecology. In addition to the reactive magnesium power, the
destroyed building also contained approximately 36 ordinus of faliamable liquids. Just outside the
destroyed building approximately 40 drums and totes of other hazardous wastes and almost 100 drums
containing magnesium powder were staged awaiting treatment. A number of these drums and totes
were damaged in the explosions.
Throughout the day Sunday, US Ecology gathered resources and formulated a plan to enter the
impacted area starting Monday, November 19°. The operational objectives are to safely remove all
drums and totes of shazardous waste from the impacted area. EPA START contractors are in route to
assist with air monitoring and oversight of the operations.
The nearest population center (Grand View, Idaho) is approximately 10 miles away and there are some
isolated rural residences approximately ½ mile from the US Ecology facility,
Media Interest: Moderate

https://www.idahostatesman.com/frees/focal/article221871790.html



Beth Sheldrake, Emergency Response Unit Manager EPA Region 10, Emergency Management Program 1200 Sxth Ave., Suite 155 Seattle, WA 98101 C: 266-890-1397 O: 206-553-0220 Sheldrake. beth@epa.gov National Response Center (800) 424-8802